


Weighing Management PC Program

- Held by a variety of programs.
- Appropriate development program at the production site.
- Using a variety of features and convenient.
- Printing function, operation, and records, data and statistics.

➤ Tester Weighing program

CH.1	1.5618	kgf
CH.2	3.2058	kgf
CH.3	5.0397	kgf
CH.4	7.7805	lbf
CH.5	9.8071	lbf
CH.6	11.665	lbf



➤ PDN20 Program

The first screenshot shows the DC VIEWER window with 'DATA VIEWER' selected. It displays a large digital scale reading of **0.5442 kgf**. Below the reading, it shows '1 Hz (1 Sample/S)', 'Save' and 'Stop' buttons, a timer at **00:00:00.0**, and 'Memory' and 'Exit' buttons.

The second screenshot shows the 'Memory Data' window. It has 'From' and 'To' fields both set to '1'. Below these is a 'Load' button and a table with multiple empty rows. At the bottom are 'Convert' and 'Exit' buttons.

➤ Truck Scale Program

The first two screenshots show the main interface of the Truck Scale Program. The top part features a large digital display showing **700kg** with a truck image in the background. Below this are several data tables and control panels.

The third screenshot shows a 'Weight Report' window. It contains two main tables: 'Weight Report' and 'Data Weighing Report'. Below these are sections for 'Weighing List per Customer' and 'Data Weighing List per Customer'.